



8515 E. Anderson Drive
Scottsdale, AZ 85255, USA

Phone: +1 480 348 6380. Fax: +1 270 5070.
www.hgnss.com

May 20, 2016

Dear valued Hemisphere GNSS Customer,

This letter confirms to your company that Hemisphere GNSS is discontinuing the manufacture of the products listed in the table below. In accordance with Hemisphere GNSS' product discontinuation policy, we are hereby giving notice of these product changes so that your company can adjust its product purchasing records.

Please note that we are no longer able to ship VS131's, but we can offer VS131-equivalent performance via the 940-3113-0 kit shown below. The VS330 offers significant upgradability through options such as multi-GNSS (GPS, GLONASS, BeiDou), multi-Frequency, Athena RTK, and our Atlas corrections service.

Hemisphere GNSS will continue to service the VS131 until the identified End-of-Repair Date. All existing online support materials will remain available and can continue to be referenced by our customers and partners until End-of-Support Date.

We thank you for your continued business. Please contact your Hemisphere GNSS representative with any questions.

End-of-Life Products:

Product Number	Description	MSRP	Final Order Date	Final Ship Date	End of Repair Date	End of Support Date
803-3025-0	VS131 Heading Receiver	n/a	n/a	n/a	6/30/18	6/30/19
940-3096-0	Vector VS131 DGNSS Receiver	\$3,400	n/a	n/a	6/30/18	6/30/19

New Replacement Products:

Product Number	Description	MSRP	Availability Date
803-3028-0	VS330 Heading Receiver	n/a	n/a
940-3113-0	Vector VS330 GNSS Receiver (w/ VS131 configuration: sFreq, GPS/GLO, 10Hz)	\$3,825	5/20/16