



TRIMBLE BD930 UPDATE

PRODUCT END OF LIFE / END OF MANUFACTURING ANNOUNCEMENT

Date: April 25, 2018

Trimble® Integrated Technologies announces this product bulletin to inform our customers of planned product migration activities surrounding our BD930 product as follows:

- The BD930 is now officially in its end of life / end of manufacturing phase.
- Trimble® does not encourage development of any new projects using the BD930.
- Trimble® cannot guarantee product supply after Q2 2018.
- Trimble® suggests BD930 customers looking for a replacement product should consider the Trimble BD940 receiver. The BD940 contains the latest Trimble Maxwell 7 technology and added support for Trimble RTX/OmniSTAR in the same mechanical package as the BD930.

Product	Part Number(s)	Description
Trimble BD930	90930-01	Trimble BD930, All options disabled, requires upgrade to output positions
	90930-03	Trimble BD930, GPS, L1 Autonomous/SBAS, 20Hz
	90930-04	Trimble BD930, GPS, L1 DGPS Base/Rover, 5Hz
	90930-05	Trimble BD930, GPS, L1 DGPS Base/Rover, 20Hz
	90930-07	Trimble BD930, GPS, L1 DGPS Rover, 20Hz
	90930-08	Trimble BD930, GPS, L1 RTK Base/Rover, 5Hz
	90930-09	Trimble BD930, GPS, L1 RTK Base/Rover, 20Hz
	90930-12	Trimble BD930, GPS, L1/L2/L5 RTK Base/Rover, 5Hz
	90930-13	Trimble BD930, GPS, L1/L2/L5 RTK Base/Rover, 20Hz
	90930-14	Trimble BD930, GPS, L1/L2/L5 RTK Rover, 5Hz
	90930-15	Trimble BD930, GPS, L1/L2/L5 RTK Rover, 20Hz
	90930-23	Trimble BD930, GPS, GLN, L1 Autonomous/SBAS, 20Hz
	90930-24	Trimble BD930, GPS, GLN, L1 DGPS Base/Rover, 5Hz
	90930-25	Trimble BD930, GPS, GLN, L1 DGPS Base/Rover, 20Hz
	90930-27	Trimble BD930, GPS, GLN, L1 DGPS Rover, 20Hz
	90930-28	Trimble BD930, GPS, GLN, L1 RTK Base/Rover, 5Hz
	90930-29	Trimble BD930, GPS, GLN, L1 RTK Base/Rover, 20Hz
	90930-32	Trimble BD930, GPS, GLN, L1/L2/L5 RTK Base/Rover, 5Hz
	90930-33	Trimble BD930, GPS, GLN, L1/L2/L5 RTK Base/Rover, 20Hz
	90930-34	Trimble BD930, GPS, GLN, L1/L2/L5 RTK Rover, 5Hz
90930-35	Trimble BD930, GPS, GLN, L1/L2/L5 RTK Rover, 20Hz	
90930-56	Trimble BD930, GPS, GLN, BDS L1 Autonomous/SBAS, 20Hz	
90930-57	Trimble BD930, GPS, GLN, BDS L1, DGPS Base/Rover, 20Hz	



Product	Part Number(s)	Description
Trimble BD930	90930-58	Trimble BD930, GPS, GLN, BDS, L1/L2/L5 RTK Base/Rover, 5Hz
	90930-59	Trimble BD930, GPS, GLN, BDS L1/L2/L5 RTK Base/Rover, 20Hz
	90930-63	Trimble BD930, GPS, GLN, GAL, BDS L1 Autonomous/SBAS, 20Hz
	90930-64	Trimble BD930, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 5Hz
	90930-65	Trimble BD930, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 20Hz
	90930-68	Trimble BD930, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 5Hz
	90930-69	Trimble BD930, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 20Hz
	90930-77	Trimble BD930, GPS, GLN, GAL, BDS L1/L2/L5 RTK Base/Rover, 20Hz
	90930-83	Trimble BD930, GPS, BDS, L1 Autonomous/SBAS, 20Hz
	90930-85	Trimble BD930, GPS, BDS, L1 DGPS Base/Rover, 20Hz
	90930-88	Trimble BD930, GPS, BDS, L1/L2/L5 RTK Base/Rover, 5Hz
	90930-89	Trimble BD930, GPS, BDS, L1/L2/L5 RTK Base/Rover, 20Hz
	90930-90	Trimble BD930, GPS, GLN, GAL, BDS L1/L2/L5, Heading Only Rover ²

Parts, Servicing and Warranty Information

The standard Trimble policy for parts, servicing and warranty applies.

Availability

The above mentioned products will be available while supplies last.



Contact NavtechGPS for product details. www.NavtechGPS.com
 +1-703-256-8900 • 800-628-0885 • info@navtechgps.com

